




Instructions

E34HJ11S25M04T04-G-CB




① *4	② *1	③ *1
④ *1	⑤ *1	⑥ *2
⑦ *1	⑧ *1 (L)	⑨ *1 (R)
⑩ *2	⑪ *1 (L)	⑫ *1 (R)
⑬ *2	⑭ *4	⑮ *1
⑯ *1	⑰ *1	⑱ *2
⑲ *1	⑳ *1	㉑ *1
㉒ *1	㉓ *1	㉔ *1
㉕ *1	㉖ *1 (L)	㉗ *1 (R)
㉘ *1	㉙ *3	㉚ *1
㉛ *2	㉜ *1	㉝ *1
㉞ *1	㉟ *1	㊱ *1
A M5-10*51	B M6-15*8	C M4-10*4
D M5-12*10	E *1	F *4
G ϕ 28-2*1	H M4-8*4	I M5-10*6 (SS)
J M5-12*8	K M10*1 (1.0)	

1




A		16 PCS
---	---	--------

2




A		4 PCS
---	---	-------

3




4




A		2 PCS
---	---	-------

5




A		5 PCS
---	--	-------

6




A		4 PCS
---	--	-------

7



H		2 PCS
E		1 PCS


8



A		2 PCS
D		6 PCS


4

9




D		4 PCS
---	--	-------

10




F		4 PCS
---	--	-------

11




C		4 PCS
---	--	-------

12




J		4 PCS
---	--	-------


13




14



15



16




6

A		4 PCS
---	---	-------


I		4 PCS
---	---	-------

17




A		8 PCS
---	---	-------

18




A		6 PCS
---	---	-------

19



J		4 PCS
---	---	-------



20





K		1 PC
---	--	------




21




22




23




24




25




26



27






28



I		4 PCS
---	---	-------



29




30



31



32




G



1 PC

33



34

